



Close-up: Illegal fitting on 12" Kokori-Eriemu delivery line at Awirhe. Picture was taken during Joint Investigation of 24<sup>th</sup> January 2012.