



Overview: Part of spill impact on 36" Npoku-Bomu pipeline right of way at Eneka. Picture was taken during Joint Investigation of 20<sup>th</sup> January 2012.



Close-up: 1<sup>st</sup> set of Illegal fittings on 36" Npoku-Bomu pipeline at Eneka. Picture was taken during Joint Investigation of 21<sup>st</sup> January 2012.



Overview: 2<sup>nd</sup> set of Illegal fittings on 36" Npoku-Bomu pipeline at Eneka. Picture was taken during Joint Investigation of 21<sup>st</sup> January 2012.