



Overview: Part of spill impact on Well head on Ubefan Well2 right of way at Kantu. Picture was taken during Joint Investigation of 13th December 2011.



Close-up: Illegal fitting on Ubefan Well2 at Kantu. Picture was taken during Joint Investigation of 13th December 2011.