



Overview: Part of spill impact on 12" Afiesere - Eriemu Delivery Line at Emeragha. Picture was taken during Joint Investigation of 31st July, 2012.



Close-up: Illegal fitting on 12" Afiesere - Eriemu Delivery Line at Emeragha. Picture was taken during Joint Investigation of 31st July, 2012