



Overview: Extent of the spill incident impact on 18" Soku - Ekulama Pipeline at Kirikakiri .  
Pictures taken during Joint Investigation of 4<sup>th</sup> March, 2011



Close-up: Spill due to illegally welded points on 18" Soku - Ekulama Pipeline at Kirikakiri.  
Picture taken during Joint Investigation of 4<sup>th</sup> March, 2011.