



Overview: Part of spill impact on KoloCreek Well3T flowline right of way at Otusega.
Picture was taken during Joint Investigation of 17th April 2012



Close up: Cut section on KoloCreek Well3T flowline at Otusega. Picture was taken
during Joint Investigation of 26th April 2012.