





Overview: Part of spill impact on 24" Nembe Creek Trunkline right of way behind Sego Manifold. Picture was taken during Joint Investigation of 27th May 2012.



Close up: Illegal fittings on 24" Nembe Creek Trunkline behind Sego Manifold. Picture was taken during Joint Investigation of 27th May 2012.



Close up: Illegal fittings on 24" Nembe Creek Trunkline behind Sego Manifold. Picture was taken during Joint Investigation of 27th May 2012.