



Overview: Part of spill impact in the vicinity of Forcados Terminal. Picture was taken during Overfly of 1st October 2013.



Overview: Oil Sheen on water in the vicinity of Forcados Terminal. Picture was taken during Overfly of 6th November 2013.