



Overview: Part of spill impact on 12" Imo River2 pipeline right of way at Owaza.  
Picture was taken during Joint Investigation of 24<sup>th</sup> April 2012.



Close up: Illegal fitting on 12" Imo River2 pipeline at Owaza. Picture was taken during  
Joint Investigation of 24<sup>th</sup> April 2012.