

Overview: Part of spill impact on 36" Npoku-Bomu trunkline right of way at Agbonchia. Picture was taken during Joint Investigation of 23rd February 2012.



<u>Close up:</u> Drilled holes on 36" Npoku-Bomu trunkline at Agbonchia. Picture was taken during Joint Investigation of 23<sup>rd</sup> February 2012.

1