



Overview: Part of the spill impact on 10" Ekulama-Sanbarth pipeline at Sanbarth. Picture taken during Joint Investigation of 28th August 2011



Close-up: Spill point due to corrosion on 10" Ekulama-Sanbarth pipeline at Sanbarth. Picture taken during Joint Investigation of 22nd September, 2011