



Overview: Part of spill impact on 28" Nkpoku-Bomu pipeline right of way at Ejamah-Ebubu. Picture was taken during site visit of 18th August 2012.



Close up: Damage due to 3rd party dredging equipment on 28" Nkpoku-Bomu pipeline at Ejamah-Ebubu. Picture was taken during Joint Investigation of 21st August 2012.