



Overview: Part of spill impact on Bukuma Well 8 at Bukuma. Picture was taken during Joint Investigation of 29th August, 2012.



Close-up: Illegal Wellhead tampering on Bukuma Well 8 at Bukuma. Picture was taken during Joint Investigation of 29th August, 2012.