



Overview: Part of spill impact on 24" Bomu-Bonny pipeline right of way at Mogho. Picture was taken during Joint Investigation of 6<sup>th</sup> May 2012.



Close up: Hacksaw cut on 24" Bomu-Bonny pipeline at Mogho. Picture was taken during Joint Investigation of 6<sup>th</sup> May 2012.