



Close up: Failed drain valve on 30" Sanbarth-Cawthorne Channel Manifold holding tank at Adamakiri. Picture was taken during Joint Investigation of 2nd October 2013.



Close up: Failed drain valve on 30" Sanbarth-Cawthorne Channel Manifold holding tank at Adamakiri. Picture was taken during Joint Investigation of 2nd October 2013.