



Overview: Part of spill impact on 16" Eriemu – UPS pipeline right of way at Ekrejebor. Picture was taken during Joint Investigation of 4th May 2012.



Close up: Illegal fitting on 16" Eriemu – UPS pipeline at Ekrejebor. Picture was taken during Joint Investigation of 4th May 2012.