



Close-up: Explosive tear on submerged crude loading hose from SBM2 at Forcados Crude Loading Platform .
Picture was taken during Joint Investigation of 26th Aug. 2012.