



Overview: Extent of the spill incident impact at Kolocreek well 21T flow line route in Kolocreek . Picture was taken during JIV of 29th April, 2011



Close-up: Cut section of flow line on Kolocreek well 21T. Picture was taken during JIV of 29th April, 2011



Overview: Missing section of flow line on Kolocreek well 21T flow line route in Kolocreek.
Picture was taken during JIV of 29th April, 2011



Close-up: Discarded used hacksaw blade can be seen beside cut section of flow line on Kolocreek well 21T.