



Overview: Part of spill impact on 24" Bomu-Bonny pipeline right of way at Bodo West. Picture was taken during Joint Investigation of 30th June 2012.



Close up: Spill point on 24" Bomu-Bonny pipeline at Bodo West. Picture was taken during Joint Investigation of 30th June 2012.



Close up: Spill point on 24" Bomu-Bonny pipeline at Bodo West. Picture was taken during Joint Investigation of 30th June 2012.