



Overview: Spill location on 6" Obigbo North pipeline right of way at KomKom. Picture taken during Joint Investigation of 4<sup>th</sup> October, 2011



Close-up: Illegal fitting on 6" Obigbo North pipeline at KomKom. Picture taken during Joint Investigation of 4<sup>th</sup> October, 2011