



Close up: Hacksaw cut on Ubie Well5L flowline at Idu-Ekpeye. Picture was taken during Joint Investigation of 14th August 2012.