



Close up: Failed clamp on 24" UPS-Rapele pipeline at Ugbokodo. Picture was taken during Joint Investigation of 1st March 2012.