



Overview: Part of spill impact on 24" Nkpoku-Bomu pipeline right of way at Kira. Picture was taken during Joint Investigation of 17th August 2012.



Close up: Illegal fitting on 24" Nkpoku-Bomu pipeline at Kira. Picture was taken during Joint Investigation of 17th August 2012.