



Overview: Part of spill impact on 24" Nkpoku-Bomu pipeline right of way at Nonwa. Picture was taken during Joint Investigation of 23<sup>rd</sup> August 2012



Close up: Hacksaw cut on 24" Nkpoku-Bomu pipeline at Nonwa. Picture was taken during Joint Investigation of 23<sup>rd</sup> August 2012.