



Overview: Part of spill impact on 24" Nembe Creek pipeline right of way at Tora-Twenikiri. Picture taken during Joint Investigation of 20th August, 2011.



Close-up: Spill due to clamp failure on 24" Nembe Creek pipeline at Tora-Twenikiri. Picture taken during Joint Investigation of 26th August, 2011.