



Overview: Extent of the spill incident impact at Nun River Well 15 Flowline route in Onyoma.  
Picture was taken during JIV of 18 January 2011



Close-up: Leak from a hole on Nun River Well 15 Flowline in Onyoma . Picture was taken during JIV of 18 January 2011