



Overview: Extent of the spill incident impact on Uzere Well 19S. Pictures taken during Joint Investigation of 19th April, 2011



Close-up: Spill point showing Hacksaw cut on Uzere Well 9s Picture taken during Joint Investigation of 21st April, 2011.