



Overview: Part of spill impact on 10" Diebu creek-Nun River Pipeline route at Oporoma
. Picture taken during Joint Investigation of 1st September, 2011



Close-up: Spill due to drilled hole on 10" Diebu creek-Nun River Pipeline at Oporoma.
Picture taken during Joint Investigation of 1st September, 2011