



Overview: Part of spill impact on 8 inch Ughelli West – UPS Delivery Line at Ekakpamre. Picture was taken during Joint Investigation of 11<sup>th</sup> Dec. 2012.



Close-up: Damaged section on 8 inch Ughelli West – UPS Delivery Line at Ekakpamre. Picture was taken during Joint Investigation of 11<sup>th</sup> Dec. 2012.