



Overview: Part of spill impact on 28" Bomu-Bonny pipeline right of way at Mogho. Picture was taken during Joint Investigation of 26th August 2012



Close up: Hacksaw cut on 28" Bomu-Bonny pipeline at Mogho. Picture was taken during Joint Investigation of 26th August 2012



Close up: Hacksaw cut on 28" Bomu-Bonny pipeline at Mogho. Picture was taken during Joint Investigation of 26th August 2012