



Overview: Part of the spill impact on Cawthorne channel Well 45T flowline at Mbiama.
Picture taken during Joint Investigation of 23rd June, 2011



Close-up: Spill point due to corrosion on Cawthorne channel Well 45T flowline at Mbiama.
Picture taken during Joint Investigation of 23rd June, 2011