



Overview: Part of spill impact on 8" Umuechem-Nkpoku pipeline right of way at Omusele. Picture was taken during Joint Investigation of 26<sup>th</sup> July 2012.



Close up: Illegal fittings on 8" Umuechem-Nkpoku pipeline at Omusele. Picture was taken during Joint Investigation of 26<sup>th</sup> July 2012.