



Overview: Part of spill impact on Buguma-Alakiri trunkline right of way at Abiama. Picture taken during Joint Investigation of 19<sup>th</sup> August, 2011.



Close-up: Spill due to hacksaw cut on Buguma-Alakiri trunkline right of way at Abiama. Picture taken during Joint Investigation of 23<sup>rd</sup> August, 2011.