



Overview: Extent of the spill incident impact at 36" Rumuekpe-Nkpoku Pipeline route in Aluu . Picture was taken during JIV of 29th April, 2011



Close-up: Another view of spill incident impact at 36" Rumuekpe-Nkpoku Pipeline route in Aluu . Picture was taken during JIV of 29th April, 2011



Overview: Illegally welded points on 36" Rumuekpe-Nkpoku Pipeline in Aluu. Picture was taken during JIV of 29th April, 2011



Close-up: Illegally welded points on 36" Rumuekpe-Nkpoku Pipeline in Aluu. Picture was taken on 30th April, 2011