



Overview: Extent of spill impact on the 10in Diebu Creek – Nun river pipeline at Nun river. Picture was taken during JIV of 18 May 2011



Overview : Extent of spill impact on the 10in Diebu Creek – Nun river pipeline at Nun river. Picture was taken during JIV of 18 May 2011





Close-up: Hacksaw cuts on the 10 inch Diebu Creek – Nun river pipeline at Nun river. Picture was taken during JIV of 18 May 2011.



Close-up: Damage due to explosion evident on the 10 inch Diebu Creek – Nun river pipeline at Nun river. The visible clamp is from an earlier spill response.