



Overview: Part of spill impact on Bonny Terminal Platform Single Point Mooring II Hose at Bonny.  
Picture was taken during Overfly on 11<sup>th</sup> Dec. 2012.



Close-up: location of failed hose on Bonny Terminal Platform Single Point Mooring II Hose at Bonny.  
Picture was taken during Overfly on 11<sup>th</sup> Dec. 2012.