



Overview: Extent of the spill incident impact at Otamiri Well 7 Flowline route in Umuechem.
Picture was taken during JIV of 18 January 2011



Close-up: Leak from a pinhole at 7'o'clock on Otamiri Well 7 Flowline in Umuechem.
Picture was taken during JIV of 18 January 2011