



Overview: Part of spill impact on 8" Isimiri-Imo Gate pipeline right of way at Obiakpu. Picture was taken during Joint Investigation of 22nd December 2012.



Close up: Illegal fitting on 8" Isimiri-Imo Gate pipeline at Obiakpu. Picture was taken during Joint Investigation of 22nd December 2012.