



Overview: Part of spill impact on 16" Egbema-Assa pipeline right of way at Assa. Picture was taken during Joint Investigation of 7<sup>th</sup> April 2012.



Close up: Failed clamp on 16" Egbema-Assa pipeline at Assa. Picture was taken during Joint Investigation of 7<sup>th</sup> April 2012.