



Overview: Part of spill impact on 36" Nkpoku-Ogale pipeline right of way at Akpajo
Picture was taken during Joint Investigation of 8th August 2012.



Close up: Failed clamp on 36" Nkpoku-Ogale pipeline at Akpajo
Picture was taken during Joint Investigation of 8th August 2012.