



Overview: Part of spill impact on Oroni Well7 flowline right of way at Igbi. Picture was taken during Joint Investigation of 15th December, 2011..



Close-up: Hacksaw cuts on Oroni Well7 flowline at Igbi. Picture was taken during Joint Investigation of 15th December, 2011.



Close-up: Hacksaw cut on Oroni Well7 flowline at Igbide. Picture was taken during Joint Investigation of 15th December, 2011.