



Overview: Part of spill impact on Nembe 2 Well 39S flowline at Kenkiamabogo. Picture was taken during Joint Investigation of 13<sup>th</sup> September 2012.



Close-up: Corrosion on Nembe 2 Well 39S flowline at Kenkiamabogo. Picture was taken during Joint Investigation of 13<sup>th</sup> September 2012.