



Overview: Part of spill impact on 8" Etelebou-Kolocreek pipeline right of way at Biogbolo. Picture was taken during Joint Investigation of 13th April 2012.



Close up: Evidence of corrosion on 8" Etelebou-Kolocreek pipeline at Biogbolo. Picture was taken during Joint Investigation of 13th April 2012.