



Overview: Part of spill impact on 6" Obigbo North pipeline right of way at Ogale. Picture was taken during Joint Investigation of 12th November, 2011.



Close-up: Illegal fitting on 6" Obigbo North pipeline at Ogale. Picture was taken during Joint Investigation of 12th November, 2011.