



Overview: Part of spill impact on 12" Afiesere-Eriemu delivery line right of way at Gana. Picture was taken during Joint Investigation of 23<sup>rd</sup> October 2012.



Close up: Leak from vent valve on 12" Afiesere-Eriemu delivery line at Gana. Picture was taken during Joint Investigation of 23<sup>rd</sup> October 2012.