

Overview: Part of spill impact at Obelle Flowstation at Obelle. Picture taken during Joint Investigation of 11th August 2011.



<u>Close-up:</u> Spill due to saver pit overflow at Obelle Flowstation at Obelle. Picture taken during Joint Investigation of 11th August 2011.

1