



Overview: Part of spill impact on 16" Egbema-Assa pipeline at Assa. Picture was taken during Joint Investigation of 2nd February 2012.



Close-up: Illegal fittings on 16" Egbema-Assa pipeline at Assa. Picture was taken during Joint Investigation of 2nd February 2012.