



Overview: Extent of the spill incident impact at Agbada Well 58 Flowline route in Agbada.
Picture was taken during JIV of 18 January 2011



Close-up: Leak from a pinhole at 6'o'clock on Agbada Well 58 Flowline in Agbada .
Picture was taken during JIV of 18 January 2011