



Close up: Hacksaw cuts on Oroni Wells 7L, 3L & 3S flowlines at Igbiide. Picture was taken during Joint Investigation of 22nd June 2012.