



Overview: Part of spill impact on 10" Utorogu-UPS trunkline right of way at Out-Jeremi. Picture was taken during Joint Investigation of 28<sup>th</sup> July 2012.



Close up: Illegal fitting on 10" Utorogu-UPS trunkline at Out-Jeremi. Picture was taken during Joint Investigation of 28<sup>th</sup> July 2012.